



Consumer Response Group

6500 W. Cortland Street * Chicago, IL 60707 * Phone: 773-889-8870 * FAX: 773-622-2269

January 4, 2008

Page 1 of 1

TECHNICAL SERVICE BULLETIN

10055

MODEL(S): 29 LTD SE

DESCRIPTION: Excessive acoustic feedback when transmitting with talkback.

ACTION: Change R67 to 68Ω.

ADJUSTMENTS: None.

NOTES: None.