

# MR HH125

## Power-on reset

Hold both the DW button and the MEM/ESC button, then power on.

Continue holding the buttons until the display test is done.

The display should show “IN”.

Power off & back on.