



Consumer Response Group

6500 W. Cortland Street * Chicago, IL 60707 * Phone: 773-889-8870 * FAX: 773-622-2269

March 12, 2014

Page 1 of 1

TECHNICAL SERVICE BULLETIN 10085

- MODEL(S):** All versions of the 29 LTD with the “29 LTD” PLL IC chip (IC1)
- DESCRIPTION:** The original “29 LTD” PLL chip (IC1) came in a 22-pin package. This configuration has been discontinued by the manufacturer and the chip is now being produced in a 24-pin version.
- Part number 307-145-9-001 is discontinued and no longer available.
The Cobra part number for the new 24-pin chip is 307-145-9-001NP.
- ACTION:** The 22-pin version of IC1 is no longer available. It is possible to use the 24-pin version as a replacement. Use a pair of cutters to remove pin 12 and pin 13, and then install the chip. It will function exactly as the original.
- ADJUSTMENTS:** None.
- NOTES:** None.